



Service History Report

March 8, 2022
50097

Jonathans Landing

Date Range:

Toll Free: (888) 480-5253
Fax: (888) 358-0088
www.solitudelakemanagement.com

Service Date 12/2/2021 11678
No. PI-A00728352
Order No. SMOR-543525
Contract No. SVR56453

Technician Name and State License #s
Gary Navalance
Luis Santiago

Table with 4 columns: Service Item #, Description, Lake No., Lake Name. Row 1: 11678-WATERWAY, JONATHAN'S LANDING POA Waterway, Waterway. Includes Technician's Comments and General Comments.

Service Date 12/6/2021 11678
No. PI-A00728353
Order No. SMOR-543527
Contract No. SVR56456

Technician Name and State License #s
Gary Navalance
Luis Santiago

Table with 4 columns: Service Item #, Description, Lake No., Lake Name. Row 1: 11678-WATERWAY, JONATHAN'S LANDING POA Waterway, Waterway. Includes Technician's Comments and General Comments.

Service Date 12/10/2021 11678
No. PI-A00726577
Order No. SMOR-537549
Contract No. SVR56045

Technician Name and State License #s
Dan Cook

Table with 4 columns: Service Item #, Description, Lake No., Lake Name. Row 1: 11678-AERATOR-001, Jonathan's Landing - Aerator #1. Includes Technician's Comments and General Comments.

Aerator Amps		Aerator Voltage	
Air Delivery Tubing	OK	Air Filter	OK
Control Valves	OK	Cooling Fan	OK
Diffusers Fixed/Replaced		Diffusers Running	
Inlet Check Valve	OK	Muffler Jar	OK
Pressure	OK	Pressure Gauge	OK
Pressure Relief Valve	OK		

Service Item #	Description	Lake No.	Lake Name
11678-AERATOR-002	Jonathan's Landing - Aerator #2		
Technician's Comments:	Fan not working at arrival, installed new fan, new muffler/ filter, capacitor and replaced cracked airline, tested all systems and everything is working properly.		
General Comments:	Serviced Aeration System		
Aerator Amps		Aerator Voltage	
Air Delivery Tubing	OK	Air Filter	OK
Control Valves	OK	Cooling Fan	OK
Diffusers Fixed/Replaced		Diffusers Running	
Inlet Check Valve	OK	Muffler Jar	OK
Pressure	OK	Pressure Gauge	OK
Pressure Relief Valve	OK		

Service Item #	Description	Lake No.	Lake Name
11678-AERATOR-003	Jonathan's Landing - Aerator #3		
Technician's Comments:	Cleaned out cabinet and muffler intake valves, tested all systems and everything is working properly.		
General Comments:	Serviced Aeration System		
Aerator Amps		Aerator Voltage	
Air Delivery Tubing	OK	Air Filter	OK
Control Valves	OK	Cooling Fan	OK
Diffusers Fixed/Replaced		Diffusers Running	
Inlet Check Valve	OK	Muffler Jar	OK
Pressure	OK	Pressure Gauge	OK
Pressure Relief Valve	OK		

Service Item #	Description	Lake No.	Lake Name
11678-AERATOR-004	Jonathan's Landing - Aerator #4		
Technician's Comments:	Fan not working at arrival, installed new fan and replaced cracked airline, tested all systems and everything is working properly. Also installed new muffler/ filter.		
General Comments:	Serviced Aeration System		
Aerator Amps		Aerator Voltage	
Air Delivery Tubing	OK	Air Filter	OK
Control Valves	OK	Cooling Fan	OK
Diffusers Fixed/Replaced		Diffusers Running	
Inlet Check Valve	OK	Muffler Jar	OK
Pressure	OK	Pressure Gauge	OK
Pressure Relief Valve	OK		

Service Item #	Description	Lake No.	Lake Name
11678-AERATOR-005	Jonathan's Landing - Aerator #5		
Technician's Comments:	Fan with bad bearings, installed new fan and new muffler/ filter, tested all systems everything is working properly.		
General Comments:	Serviced Aeration System		
Aerator Amps		Aerator Voltage	
Air Delivery Tubing	OK	Air Filter	OK
Control Valves	OK	Cooling Fan	OK

Diffusers Fixed/Replaced		Diffusers Running	
Inlet Check Valve	OK	Muffler Jar	OK
Pressure	OK	Pressure Gauge	OK
Pressure Relief Valve	OK		

Service Item #	Description	Lake No.	Lake Name
11678-AERATOR-006	Jonathan's Landing - Aerator #6		
Technician's Comments:	Cleaned out cabinet and muffler/ filter inlet valves, tested all systems and everything is working properly.		
General Comments:	Serviced Aeration System		
Aerator Amps		Aerator Voltage	
Air Delivery Tubing	OK	Air Filter	OK
Control Valves	OK	Cooling Fan	OK
Diffusers Fixed/Replaced		Diffusers Running	
Inlet Check Valve	OK	Muffler Jar	OK
Pressure	OK	Pressure Gauge	OK
Pressure Relief Valve	OK		

Service Item #	Description	Lake No.	Lake Name
11678-AERATOR-007	Jonathan's Landing - Aerator #7		
Technician's Comments:	Cleaned out cabinet and muffler inlet valves, tested all systems and everything is working properly.		
General Comments:	Serviced Aeration System		
Aerator Amps		Aerator Voltage	
Air Delivery Tubing	OK	Air Filter	OK
Control Valves	OK	Cooling Fan	OK
Diffusers Fixed/Replaced		Diffusers Running	
Inlet Check Valve	OK	Muffler Jar	OK
Pressure	OK	Pressure Gauge	OK
Pressure Relief Valve	OK		

Service Item #	Description	Lake No.	Lake Name
11678-AERATOR-008	Jonathan's Landing - Aerator #8		
Technician's Comments:	Cleaned out cabinet and muffler inlet valves, tested all systems and everything is working properly.		
General Comments:	Serviced Aeration System		
Aerator Amps		Aerator Voltage	
Air Delivery Tubing	OK	Air Filter	OK
Control Valves	OK	Cooling Fan	OK
Diffusers Fixed/Replaced		Diffusers Running	
Inlet Check Valve	OK	Muffler Jar	OK
Pressure	OK	Pressure Gauge	OK
Pressure Relief Valve	OK		

Service Item #	Description	Lake No.	Lake Name
11678-AERATOR-009	Jonathan's Landing - Aerator #9		
Technician's Comments:	Cleaned out cabinet and tested all systems and everything is working properly.		
General Comments:	Serviced Aeration System		
Aerator Amps		Aerator Voltage	
Air Delivery Tubing	OK	Air Filter	OK
Control Valves	OK	Cooling Fan	OK
Diffusers Fixed/Replaced		Diffusers Running	
Inlet Check Valve	OK	Muffler Jar	OK
Pressure	OK	Pressure Gauge	OK

Pressure Relief Valve OK

Service Item #	Description	Lake No.	Lake Name
11678-FOUNTAIN-001	Jonathan's Landing - Fountain #1		
Technician's Comments:	Tested all circuits and everything is working properly.		
General Comments:	Serviced Fountain		
Fountain Amps	13	Fountain Voltage	242/121
GFCI Breaker Test	OK	Control Breaker	OK
Contactora (Starter)	OK	Motor Overload	OK
Fountain Power Cable	OK	Fuses	OK
Fountain-Timer	OK	Shaft Propeller Impeller	OK
Clean Debris Screen	OK	Clean Nozzles	OK
Fountain Disconnect	OK	Lighting Amps	
Lighting Voltage		No. of Lights Burned Out	
No. of Lights Replaced		Clean Lights	OK
Lighting Timer	OK	Lighting Power Cable	OK
Fixtures	OK	Lenses/Seals	OK
Lighting Disconnect	OK		

Service Item #	Description	Lake No.	Lake Name
11678-FOUNTAIN-002	Jonathan's Landing - Fountain #2		
Technician's Comments:	Tested all circuits and everything is working properly.		
General Comments:	Serviced Fountain		
Fountain Amps	11.5	Fountain Voltage	242/119
GFCI Breaker Test	OK	Control Breaker	OK
Contactora (Starter)	OK	Motor Overload	OK
Fountain Power Cable	OK	Fuses	OK
Fountain-Timer	OK	Shaft Propeller Impeller	OK
Clean Debris Screen	OK	Clean Nozzles	OK
Fountain Disconnect	OK	Lighting Amps	
Lighting Voltage		No. of Lights Burned Out	
No. of Lights Replaced		Clean Lights	OK
Lighting Timer	OK	Lighting Power Cable	OK
Fixtures	OK	Lenses/Seals	OK
Lighting Disconnect	OK		

Service Item #	Description	Lake No.	Lake Name
11678-FOUNTAIN-003	Jonathan's Landing - Fountain #3		
Technician's Comments:	Tested all circuits and everything is ok.		
General Comments:	Serviced Fountain		
Fountain Amps	16.2/1.2ma	Fountain Voltage	242/119
GFCI Breaker Test	OK	Control Breaker	OK
Contactora (Starter)	OK	Motor Overload	OK
Fountain Power Cable	OK	Fuses	OK
Fountain-Timer	OK	Shaft Propeller Impeller	OK
Clean Debris Screen	OK	Clean Nozzles	OK
Fountain Disconnect	OK	Lighting Amps	
Lighting Voltage		No. of Lights Burned Out	
No. of Lights Replaced		Clean Lights	OK
Lighting Timer	OK	Lighting Power Cable	OK
Fixtures	OK	Lenses/Seals	OK

Lighting Disconnect OK

Service Item #	Description	Lake No.	Lake Name
11678-FOUNTAIN-004	Jonathan's Landing - Fountain #4		
Technician's Comments:	Tested all circuits and everything is working properly.		
General Comments:	Serviced Fountain		
Fountain Amps	16.2	Fountain Voltage	241/120
GFCI Breaker Test	OK	Control Breaker	OK
Contactora (Starter)	OK	Motor Overload	OK
Fountain Power Cable	OK	Fuses	OK
Fountain-Timer	OK	Shaft Propeller Impeller	OK
Clean Debris Screen	OK	Clean Nozzles	OK
Fountain Disconnect	OK	Lighting Amps	
Lighting Voltage		No. of Lights Burned Out	
No. of Lights Replaced		Clean Lights	OK
Lighting Timer	OK	Lighting Power Cable	OK
Fixtures	OK	Lenses/Seals	OK
Lighting Disconnect	OK		

Service Item #	Description	Lake No.	Lake Name
11678-FOUNTAIN-005	Jonathan's Landing - Fountain #5		
Technician's Comments:	Pump megging bad a quote for a new pump will be provided.		
General Comments:	Serviced Fountain		
Fountain Amps	Pump megging bad	Fountain Voltage	240/121
GFCI Breaker Test	OK	Control Breaker	OK
Contactora (Starter)	OK	Motor Overload	OK
Fountain Power Cable	OK	Fuses	OK
Fountain-Timer	OK	Shaft Propeller Impeller	OK
Clean Debris Screen	OK	Clean Nozzles	OK
Fountain Disconnect	OK	Lighting Amps	
Lighting Voltage		No. of Lights Burned Out	
No. of Lights Replaced		Clean Lights	OK
Lighting Timer	OK	Lighting Power Cable	OK
Fixtures	OK	Lenses/Seals	OK
Lighting Disconnect	OK		

Service Item #	Description	Lake No.	Lake Name
11678-FOUNTAIN-006	Jonathan's Landing - Fountain #6		
Technician's Comments:	Tested all circuits and everything is working properly.		
General Comments:	Serviced Fountain		
Fountain Amps	8.3	Fountain Voltage	242/119
GFCI Breaker Test	OK	Control Breaker	OK
Contactora (Starter)	OK	Motor Overload	OK
Fountain Power Cable	OK	Fuses	OK
Fountain-Timer	OK	Shaft Propeller Impeller	OK
Clean Debris Screen	OK	Clean Nozzles	OK
Fountain Disconnect	OK	Lighting Amps	
Lighting Voltage		No. of Lights Burned Out	
No. of Lights Replaced		Clean Lights	OK
Lighting Timer	OK	Lighting Power Cable	OK
Fixtures	OK	Lenses/Seals	OK

Lighting Disconnect OK

Service Item #	Description	Lake No.	Lake Name
11678-FOUNTAIN-020	Circulation Unit #2		
Technician's Comments:	Could not find circulator unable to pull up off bottom, motor showing amps butno water movement.		
General Comments:	Serviced Aeration System		
Fountain Amps			Fountain Voltage
GFCI Breaker Test	OK		Control Breaker OK
Contactora (Starter)	OK		Motor Overload OK
Fountain Power Cable	OK		Fuses OK
Fountain-Timer	OK		Shaft Propeller Impeller OK
Clean Debris Screen	OK		Clean Nozzles OK
Fountain Disconnect	OK		

Service Item #	Description	Lake No.	Lake Name
11678-FOUNTAIN-021	Circulation Unit #1		
Technician's Comments:	Tested all circuits and everything is working properly.		
General Comments:	Serviced Aeration System		
Fountain Amps			Fountain Voltage
GFCI Breaker Test	OK		Control Breaker OK
Contactora (Starter)	OK		Motor Overload OK
Fountain Power Cable	OK		Fuses OK
Fountain-Timer	OK		Shaft Propeller Impeller OK
Clean Debris Screen	OK		Clean Nozzles OK
Fountain Disconnect	OK		

Service Date 12/10/2021 11678
No. PI-A00727258
Order No. SMOR-544828
Contract No. SVR56045
Technician Name and State License #s
Dan Cook

Service Item #	Description	Lake No.	Lake Name
11678-AERATOR-001	Jonathan's Landing - Aerator #1		
Technician's Comments:	Tested all systems and everything is working properly.		
General Comments:	Serviced Aeration System		
Pressure Relief Valve	OK		

Service Date 12/16/2021 11678
No. PI-A00728889
Order No. SMOR-545614
Contract No. SVR56453
Technician Name and State License #s
Gary Navalance
Luis Santiago

Service Item #	Description	Lake No.	Lake Name
11678-WATERWAY	JONATHAN'S LANDING POA Waterway		Waterway
Technician's Comments:	Inspect all waterways, high winds today. Only water testing done.		
General Comments:	Inspected Lake		
Inspected for Aquatic Weeds			OK
Inspected for Undesirable Shoreline Vegetation			OK
Inspected for algae			OK
Trash & Light Debris Removal			OK

=====

Service Date 12/21/2021 **11678**

No. PI-A00730500

Order No. SMOR-545782

Contract No. SVR56453

Technician Name and State License #s
Gary Navalance
Luis Santiago

Service Item #	Description	Lake No.	Lake Name
11678-WATERWAY	JONATHAN'S LANDING POA Waterway		Waterway
Technician's Comments:	Inspect all waterways, high winds and rain squalls not allowing for treatments and also water testing. Will resume next month!		
General Comments:	Inspected Lake		
Inspected for Aquatic Weeds			OK
Inspected for Undesirable Shoreline Vegetation			OK
Inspected for algae			OK
Trash & Light Debris Removal			OK

=====

Service Date 1/5/2022 **11678**

No. PI-A00733962

Order No. SMOR-554085

Contract No. SVR56453

Technician Name and State License #s
Gary Navalance
Luis Santiago

Service Item #	Description	Lake No.	Lake Name
11678-WATERWAY	JONATHAN'S LANDING POA Waterway		Waterway
Technician's Comments:	Inspect all waterways, treat NE finger canal on #3 for heavy eelgrass growth at perimeter. Entire lake #3 is matted out with eelgrass and extra chemical is needed to maintain problem! Also water testing done weekly.		
General Comments:	Inspected Lake		
Inspected for Aquatic Weeds			Treated
Inspected for Undesirable Shoreline Vegetation			OK
Inspected for algae			Treated
Trash & Light Debris Removal			OK

=====

Service Date 1/5/2022 **11678**

No. PI-A00746748

Order No. SMOR-554086

Contract No. SVR56454

Technician Name and State License #s
Omar Aquino-Sepulveda

Service Item #	Description	Lake No.	Lake Name
11678-SHORELINE	JONATHAN'S LANDING POA Shoreline		Shoreline
Technician's Comments:	sprayed lake 2 duckweed and cut removal grass burned		
General Comments:	Inspected Lake		
Littoral Shelf Maintenance			Treated

=====

Service Date	1/10/2022	11678
No.	PI-A00734199	
Order No.	SMOR-552364	
Contract No.	SVR56045	
Technician Name and State License #s		
	Dan Cook	

Service Item #	Description	Lake No.	Lake Name
11678-AERATOR-001	Jonathan's Landing - Aerator #1		
Technician's Comments:	Aerator is not working and we were unable to pull system off bottom of lake.		
General Comments:	Serviced Aeration System		
Pressure Relief Valve		OK	

=====

Service Date	1/12/2022	11678
No.	PI-A00742463	
Order No.	SMOR-554087	
Contract No.	SVR56456	
Technician Name and State License #s		
	Gary Navalance	

Service Item #	Description	Lake No.	Lake Name
11678-WATERWAY	JONATHAN'S LANDING POA Waterway		Waterway
Technician's Comments:	Inspect all waterways with buggy today, #3 few coves loaded with floatingeelgrass which will be removed with Weedoo tomorrow where accessible. Few areaswill need manually raked out by crew!		
General Comments:	Inspected Lake		
Performed Water Quality Testing		OK	

=====

Service Date	1/20/2022	11678
No.	PI-A00745057	
Order No.	SMOR-554452	
Contract No.	SVR56453	
Technician Name and State License #s		
	Gary Navalance	
	Luis Santiago	

Service Item #	Description	Lake No.	Lake Name
11678-WATERWAY	JONATHAN'S LANDING POA Waterway		Waterway
Technician's Comments:	Inspect all waterways, weekly water tests performed. Mechanical removal lastweek in certain areas look good! Manually rake out algae at perimeter in #4.		
General Comments:	Inspected Lake		
Inspected for Aquatic Weeds		OK	
Inspected for Undesirable Shoreline Vegetation		OK	
Inspected for algae		Removed for repair	
Trash & Light Debris Removal		OK	

=====

Service Date 1/26/2022 **11678**

No. PI-A00747518

Order No. SMOR-555775

Contract No. SVR56453

Technician Name and State License #s

Gary Navalance
Luis Santiago

Service Item #	Description	Lake No.	Lake Name
11678-WATERWAY	JONATHAN'S LANDING POA Waterway		Waterway
Technician's Comments:	Inspect all waterways, start algae treatments on SE section of #3 today. Growth on top of floating/submersed eelgrass. Weekly water testing also done!		
General Comments:	Inspected Lake		
Inspected for Aquatic Weeds			OK
Inspected for Undesirable Shoreline Vegetation			OK
Inspected for algae			Treated
Trash & Light Debris Removal			OK

=====

Service Date 1/28/2022 **11678**

No. PI-A00748889

Order No. SMOR-556362

Contract No. SVR56453

Technician Name and State License #s

Gary Navalance
Luis Santiago

Service Item #	Description	Lake No.	Lake Name
11678-WATERWAY	JONATHAN'S LANDING POA Waterway		Waterway
Technician's Comments:	Inspect waterways, algae forming on exposed eelgrass. Mechanical Weedoo can be used in a few areas where the floating weed growth has collected! Will run it by Angel when I get back to office, today perform weekly water tests as usual.		
General Comments:	Inspected Lake		
Inspected for Aquatic Weeds			No treatment required
Inspected for Undesirable Shoreline Vegetation			OK
Inspected for algae			No treatment required
Trash & Light Debris Removal			OK

=====

Service Date 2/1/2022 **11678**

No. PI-A00764452

Order No. SMOR-565415

Contract No. SVR56453

Technician Name and State License #s

Gary Navalance
Luis Santiago

Service Item #	Description	Lake No.	Lake Name
11678-WATERWAY	JONATHAN'S LANDING POA Waterway		Waterway
Technician's Comments:	Continue algae treatments on #3 today, waterway being done in sections to avoid any more collateral plant damage!		
General Comments:	Inspected Lake		
Inspected for Aquatic Weeds			OK
Inspected for Undesirable Shoreline Vegetation			OK
Inspected for algae			Treated

Trash & Light Debris Removal

OK

=====

Service Date **2/1/2022** **11678**

No. PI-A00750965

Order No. SMOR-555548

Contract No. SVR56454

Technician Name and State License #s
Omar Aquino-Sepulveda

Service Item #	Description	Lake No.	Lake Name
11678-SHORELINE	JONATHAN'S LANDING POA Shoreline		Shoreline

Technician's Comments: Used the Weedoo boat to clean up floating vegetation in lake 3.

General Comments: Inspected Lake

Littoral Shelf Maintenance OK

=====

Service Date **2/1/2022** **11678**

No. PI-A00760856

Order No. SMOR-563657

Contract No. SVR56454

Technician Name and State License #s
Omar Aquino-Sepulveda

Service Item #	Description	Lake No.	Lake Name
11678-SHORELINE	JONATHAN'S LANDING POA Shoreline		Shoreline

Technician's Comments: Fill-ins littoral with cannas and arrowhead in the lake 2

General Comments: Inspected Lake

Littoral Shelf Maintenance OK

=====

Service Date **2/3/2022** **11678**

No. PI-A00757689

Order No. SMOR-563187

Contract No. SVR56454

Technician Name and State License #s
Omar Aquino-Sepulveda

Service Item #	Description	Lake No.	Lake Name
11678-SHORELINE	JONATHAN'S LANDING POA Shoreline		Shoreline

Technician's Comments: Sprayed lake 2 and 3 half littoral for weed and grass .

General Comments: Inspected Lake

Littoral Shelf Maintenance Treated

=====

Service Date **2/3/2022** **11678**

No. PI-A00756500

Order No. SMOR-562538

Contract No. SVR56455

Technician Name and State License #s
Gary Navalance

Service Item #	Description	Lake No.	Lake Name
11678-WATERWAY	JONATHAN'S LANDING POA Waterway		Waterway
Technician's Comments:	Continue algae treatments today on SW section of #3, good results on SE sectionsprayed last week! Weekly water testing also performed during visit.		
General Comments:	Inspected Lake		
Algae ID & Testing done "in house"			Treated

=====

Service Date	2/9/2022	11678
No.	PI-A00758346	
Order No.	SMOR-563021	
Contract No.	SVR56453	
Technician Name and State License #s		
	Gary Navalance	
	Luis Santiago	

Service Item #	Description	Lake No.	Lake Name
11678-WATERWAY	JONATHAN'S LANDING POA Waterway		Waterway
Technician's Comments:	Inspect all waterways, finish algae treatments on #3 today as needed on northsections east and west sides! Also perform weekly water testing as usual.		
General Comments:	Inspected Lake		
Inspected for Aquatic Weeds			OK
Inspected for Undesirable Shoreline Vegetation			OK
Inspected for algae			Treated
Trash & Light Debris Removal			OK

=====

Service Date	2/15/2022	11678
No.	PI-A00764630	
Order No.	SMOR-562539	
Contract No.	SVR56456	
Technician Name and State License #s		
	Gary Navalance	
	Luis Santiago	

Service Item #	Description	Lake No.	Lake Name
11678-WATERWAY	JONATHAN'S LANDING POA Waterway		Waterway
Technician's Comments:	Inspect all waterways, respray new algae growth on SE section of #3 today.Weekly water testing also done!		
General Comments:	Inspected Lake		
Performed Water Quality Testing			OK

=====

Service Date	2/23/2022	11678
No.	PI-A00762233	
Order No.	SMOR-563955	
Contract No.	SVR56453	
Technician Name and State License #s		
	Gary Navalance	
	Luis Santiago	

Service Item #	Description	Lake No.	Lake Name
11678-WATERWAY	JONATHAN'S LANDING POA Waterway		Waterway
Technician's Comments:	Inspect all waterways, treat algae in #5/6 canal system today with buggy. Nowater tests were performed in deeper water in #3 as usual because did not haveboat today!		
General Comments:	Inspected Lake		

Inspected for Aquatic Weeds	OK
Inspected for Undesirable Shoreline Vegetation	OK
Inspected for algae	Treated
Trash & Light Debris Removal	OK

=====

Service Date	3/1/2022	11678
No.	PI-A00766312	
Order No.	SMOR-564888	
Contract No.	SVR56454	

Technician Name and State License #s
 Omar Aquino-Sepulveda

Service Item #	Description	Lake No.	Lake Name
11678-SHORELINE	JONATHAN'S LANDING POA Shoreline		Shoreline
Technician's Comments:	cut and removed weed and grass lake 2		
General Comments:	Inspected Lake		
Littoral Shelf Maintenance			OK

=====

Service Date	3/2/2022	11678
No.	PI-A00765076	
Order No.	SMOR-572652	
Contract No.	SVR56456	

Technician Name and State License #s
 Gary Navalance
 Luis Santiago

Service Item #	Description	Lake No.	Lake Name
11678-WATERWAY	JONATHAN'S LANDING POA Waterway		Waterway
Technician's Comments:	Inspect lake #3 today with boat, ALL algae back at perimeter 1-3' out. Watertesting only done today. Will start treatments next week again!		
General Comments:	Inspected Lake		
Performed Water Quality Testing			Completed per detailed contract specifications